

# FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer Anya. C. Unni<sup>o</sup>
2. Name of the School Bethlehem International school
3. Location with name of Education District/ Sub. District Mullapuzhachal, Muvattupuzha
4. Classification of Building as specified in column 4 of the application for fitness certificate and size. Emakulam  
Rcc framed Building  
1+3F - 2850<sup>2</sup> cchs
  
5. Period for which the certificate is issued 2020-21
6. Nature of defects , if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and Windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks, etc.)} NH
7. Any major defects noticed which will render the building unsafe in any manner NH
8. Whether maintenance works have been done properly Yes.
9. Whether the structure is sound or not for conducting classes Sound under normal weather

**Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.


## CERTIFICATE

certified that the school building was inspected by me on 26/05/2020 and found to be fit / unfit to conduct classes, for the period 2020-21 for the reasons stated above.

Place : Ayavane  
Date : 26/05/20

  
**Manager**  
**The Bethlehem International**

  
  
**PRINCIPAL**  
**THE BETHLEHEM INTERNATIONAL**

  
**Assistant Engineer**  
**G.D. AYAVANA**  
**TUPUZHA**



# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

..... ARYA C UNNI.....  
THE BETHLEHEM INTERNATIONAL  
MULLAPUZHACHAL P.O. MUVATTUPUZHA  
ERNAKULAM, VAZHAKULAM - 686670

Permanent structure

..... CELLAR FLOOR - 99.34m<sup>2</sup>.....  
..... GROUND FLOOR - 799.97m<sup>2</sup>.....  
..... FIRST FLOOR - 439.24m<sup>2</sup>.....  
..... TERRACE - 31.51m<sup>2</sup>.....  
..... TOTAL 1370.06m<sup>2</sup>.....

5. Period for which the certificate is issued
6. Nature of defects, if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and Windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

.....  
.....  
.....  
..... NIL.....  
.....  
.....  
.....  
.....  
.....  
..... NIL.....  
.....

..... Yes.....  
..... Sound & safe under normal weather.....

**Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on ..... 21/12/20 ..... and  
found to be fit / unfit to conduct classes, for the period ..... 2020 ..... 2021 ..... for the  
reasons stated above.

Place: ..... Ayavana .....  
Date: ..... 21/12/20 ..... (Seal)



Assistant Engineer

ASSISTANT ENGINEER  
LSGD Section  
Ayavana, Muvattupuzha

Manager

The Bethlehem International

PRINCIPAL  
THE BETHLEHEM  
INTERNATIONAL